

# Pool And Recreation Areas

Friday, December 4, 2015

Prepared For Fort Myers Beach

Identified 31 Issues




Chaz Smith

Florida League Of Cities

**FMIT Risk Control services are intended solely to identify and assess reasonable risks within the Member's insured property. However, FMIT Risk Control does not warrant or guarantee the safety of any property or condition within the Member's property and cannot guarantee additional risks will not result in loss following a Risk Control assessment. Improvements or corrections to the Member's property are solely its responsibility. Accordingly, Member acknowledges neither FMIT, its employees nor its agents shall be liable for losses related to any risk assessment provided.**





### **Basketball Hoop Repair**

Recommend repair of basketball goal


---



### **Safety Data Sheets**

Recommend keeping updated SDS for all cleaning supplies and chemicals.


---



### **Missing Cover**

Recommend replacing transition cover. Needs cover to transition between two different types of flooring as this is a tripping hazard.


---



### **Basketball Court**

Recommend floor repairs. Overall the gym floor is still in decent shape for the age of the floor.

---



### **Basketball Court**

See previous comments.



### **Broken Light In Gym ADA Bathroom**

Recommend repair of lights in ADA bathroom as this is a safety and risk hazard. I talked to staff and they did admit that they knew the lights did not work.




### **Replace Cover Of Water Fountain -tennis courts**

Recommend replacing cover of electrical outlet and water piping. This is a safety and liability hazard.



### **Entrapment Hazard At Tennis Courts**

Recommend to file down bolt or replace with proper length bolt. This hazard can cause entrapment and as well as puncture wounds to a person. This a safety and liability hazard.



### **Bench On Tennis Courts**

Recommend repair of benches as the plastic coating has worn away and not sharp rusty metal is exposed. This is a safety and liability hazard.

---



### **Tennis Courts Broken Outlet**

Recommend the replacement of electrical outlet. This is a safety and liability hazard.


---



### **Bench On Tennis Courts**

See previous comments.

---



### **Exposed Wires**


Recommend replacing cover for baseball score board for the field closes to tennis court. This is an electrical hazard.

---




### **Damaged Shed**

Recommend repair of storage shed.



### **Needs Sign For Gas Storage**

Recommend replacement of storage shed as it is at its useful life. There needs to be a sign for the storage of gasoline on the outside for fire department to have notice of gasoline.



### **Replace Shed**

See other comments. Shed had a lot of damage.



### **Useful Life Of Playground Set**

Recommend replacement of playground unit as it has met its useful life. It is uneven and materials have deteriorated.



### **Nails Coming Thru Fence**

Recommend repair of electrical outlet that is attached to post that now is missing back piece. Now nails are exposed thru the fence and could cause injury.


---



### **Replace Access Hatch**

Recommend replacement of assess hatch as it is an tripping hazard.

---



### **Damaged Fence Post**

Recommend the replacement of fence post near baseball field. This is a safety hazard will cut a patron.

---



### **Parking Lot Repair**


Recommend repair of pavement. Tripping hazard.

---




### **Light Post Panel**

Recommend repair or replacement of cover. Safety hazard.



### **Electric Room And Cooking Food**

Recommend no cooking in electric room in pool area and removal of cooking equipment. This is a safety hazard.



### **Exposed Wire Near Shower**

Recommend the removal of exposed electrical wire in the outdoor shower area of the pool



### **Need Proper Storage Hydrochloric Acid**

Recommend proper storing of emptied hydrochloride acid containers. The containers are in an open area in which a child can access. This is a safety and liability hazard.



### **Pool Slide Structure Failure**

The safety railing has deteriorated and become detached from the structure of the water slide. Recommend the repair or replacement of railing. This is a major structure failure hazard.

---



### **Pool Slide Structure Failure**

See previous comments, structure failure.


---



### **Pool Slide Stairs**

See previous comments

---



### **Pool Slide Stairs**

See previous comments, multiple repairs.


---



### **Surface Rust**

Kiddie pool play area has a lot of rust all over. Recommend repairing rust surfaces.

---



### **Missing Cover If Electrical Outlet**

Recommend replacing electrical outlet cover as it is near water.

---



### **Pool Deck Tiles**

Pool deck tiles are starting to deteriorate. Recommend repair and resurfacing of pool deck tile throughout pool area.

---